




714 TL




hietakari / sandriff




8/25 69RLM




Parts




1. x1



2. x1




3. x1




4/83 13RLM

4. 6x30 mm
x5



4/83 11RLM

5. 3.5x39 mm
x5




4/83 22RLM

6. x6




4/83 24RLM

7. 4.2x13 mm
x8




4/83 23RLM

8. x6




8/65 459LM

9. x1




8/65 319LM

10. x1




8/65 319LM

11. x1




4/83 619LM

12. x1




4/83 A19LM


13. x1



17. x1




18. x1




1/42 B0RLM

14. x1



1/42 60RLM


15. x1




8/45 12RLM

16. x1


Tools




A




B – Silicone




C




Ø6 mm
D




E




F




1




2









3







4











13



14



15

